


# Wood Inspection Services, Inc.





## State-of-the-Art Infrared Inspections!


With the constantly rising cost of utilities, this is one service you cannot afford to be without!

Thermal imaging inspections can offer you the peace of mind that typical visual inspections cannot. Using temperature-sensitive equipment, even the smallest problems can easily be detected.

\$\$\$ A picture can be worth a Thousand Dollars \$\$\$



Sometimes you can't see what was done and what was not.. Look at the above photo and can you tell how tall the contractor was?? *Note, the above areas was not insulated.*



This Infrared image shows a well insulated wall.

Please [contact us](#) for additional information and pricing information.

Call - 972/724-5550 for information today, and start saving tomorrow.

© 2004 Wood Inspection Services, Inc.  
All Rights Reserved. US Trademark